


PLAN VIEW ON ARROW
W ON FRONT END OF
BODY SIDE MEMBER

DIFFERENCE OF
LOCATION OF
COMPANION HOLES
ON OPPOSITE SIDES
OF UNDERBODY NOT
TO EXCEED $\frac{1}{64}$



BODY TOLERANCE CHART (4 DOOR MODEL) — SEDAN

ALL DIMENSIONS IN INCHES